




Connect to the middle
(NO) and com terminals.
Do not connect to the NC
terminal.



Make sure the positive power leads are connected to this side of the each diode.